US Army Corps
of Engineers®

Detroit District
P.O. Box 1027
Detroit, MI 48231-1027
(313) 226-6797
FAX - (313) 226-3519

Notice to Navigation Interests

Notice No. L06-49 Date: 6 SEPTEMBER 2006

Waterway: LAKE HURON Location: MICHIGAN

CELRE-OT-T

CONDITION OF FEDERAL NAVIGATION CHANNEL
PORT AUSTIN HARBOR

1. Surveys performed within the Federal navigation channel at Port Austin Harbor, Michigan during August 2006, indicate shoaling as shown on the back of this sheet.

2. Mariners are urged to use extreme caution in the area.

3. All inquiries should be addressed to CELRE-OT-T and should refer to Notice to Navigation Interests No. L06-49. Internet address: http://www.lre.usace.army.mil Go to: Detroit Home Page, Who We Are, Operations Office Home Page.

WILLIAM J. LEADY
Lieutenant Colonel, U.S. Army
District Engineer

Notice to the Postmaster:

It is requested that the above notice be conspicuously and continuously posted until November 30, 2006.



The information depicted on this map represents the results of surveys made on the date indicated and can only be considered as indicating the general conditions existing at that time.

Shoals indicate least available depth below LWD

All depths and project depths are referred to Low Water Datum elevation 577.5 ft. above Mean Water Level, IGLD, 1985.

Surveys taken: **August 2006**

PORT AUSTIN HARBOR, MICHIGAN

CONDITION OF CHANNEL

ISSUED: **6 September 2006**

U.S. Army Engineer District, Detroit

0ptaus.bmp