Existing Vegetation Inventory



Tree Legend

Poor or Dying — Good

- Sugar Maple
- Birch
- Oak
- Silver Maple, Norway Maple and Box Elder
- Elm
- Colorado Blue and White Spruce, Larch
- Red and Black Maple
- White and Red Pine
- Linden, American Hornbeam, Black Walnut and Black Locust
- Beech
- Malus
- Ash

Vegetation Summary

- Remove dying/poor condition trees, trees interfering with proposed upgrades and improve sight lines in the park.
- Remove trees around fountain that have become overgrown and a maintenance problem.
- Selective tree trimming and thinning at park main entrance to promote tree health and create sight lines and more open space
- Concert Area: Remove old and dying trees, focus viewing on presentation area.