



US Army Corps
of Engineers

Detroit District
P.O. Box 1027
Detroit, MI 48231-1027
(313) 226-6796
FAX - (313) 226-3519

Notice to Navigation Interests

Notice No. L02-50

Date: 20 AUGUST 2002

Waterway: LAKE SUPERIOR

Location: MICHIGAN

CELRE-OT-T


CONDITION OF FEDERAL NAVIGATION CHANNEL
MARQUETTE HARBOR

1. Condition surveys performed within the Federal navigation channel at the Marquette Harbor, Michigan during July 2002, indicate shoaling as shown on the back of this sheet.
2. Mariners are urged to use extreme caution in the area.
3. All inquiries should be addressed to CELRE-OT-T and should refer to Notice to Navigation Interests No. L02-50. Internet address: <http://huron.lre.usace.army.mil/OandM/o&m.html>

THOMAS H. MAGNESS
Lieutenant Colonel, U.S. Army
District Engineer

Notice to the Postmaster:

It is requested that the above notice be conspicuously and continuously posted until November 30, 2002.



THE INFORMATION DEPICTED ON THIS DRAWING REPRESENTS THE RESULTS OF SURVEYS MADE ON THE DATES INDICATED AND CAN ONLY BE CONSIDERED AS INDICATING THE GENERAL CONDITIONS EXISTING AT THAT TIME.

ALL SOUNDINGS ARE IN FEET AND ARE REFERENCED TO LOW WATER DATUM ELEVATION 601.1 FT. ABOVE MEAN SEA LEVEL IGLD, 1985. (HYDRAULIC CORRECTOR APPLIED).

SHOALS INDICATE LEAST AVAILABLE DEPTH BELOW IGLD.

SURVEYS TAKEN: JULY 2002

MARQUETTE HARBOR, MICHIGAN

CONDITION OF CHANNEL

ISSUED: 20 AUGUST 2002

U.S. Army Engineer District, Detroit