



**US Army Corps
of Engineers®**

Detroit District
P.O. Box 1027
Detroit, MI 48231-1027
(313) 226-6797
FAX - (313) 226-3519

Notice to Navigation Interests

Notice No. L04-17

Date: 12 MAY 2004

Waterway: LAKE HURON

Location: MICHIGAN

CELRE-OT-T


CONDITION OF FEDERAL NAVIGATION CHANNEL
HAMMOND BAY HARBOR

1. Condition surveys performed within the Federal navigation channel at Hammond Bay Harbor, Michigan during May 2004, indicate shoaling as shown on the back of this sheet.
2. Mariners are urged to use extreme caution in the area.
3. All inquiries should be addressed to CELRE-OT-T and should refer to Notice to Navigation Interests No. L04-17. Internet address: <http://www.lre.usace.army.mil> Go to: Detroit Home Page, Who We Are, Operations Home Page.

THOMAS H. MAGNESS
Lieutenant Colonel, U.S. Army
District Engineer

Notice to the Postmaster:

It is requested that the above notice be conspicuously and continuously posted until November 30, 2004.



PRESQUE ISLE COUNTY

The information depicted on this map represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.

Surveys taken: MAY 2004

 Shoals indicate least available depth below LWD

Soundings are in feet and are referred to Low Water Datum 576.8 ft. above Mean water level at Father Point, Quebec, IGLD, 1955.

HAMMOND BAY HARBOR, MICHIGAN

CONDITION OF CHANNEL

ISSUED: 12 MAY 2004

U.S. Army Engineer District, Detroit