



US Army Corps  
of Engineers.

# Notice to Navigation Interests

---

Detroit District  
P.O. Box 1027  
Detroit, MI 48231-1027  
(313) 226-6797  
FAX - (313) 226-3519

Notice No. L04-64

Date: 10 SEPTEMBER 2004

Waterway: LAKE MICHIGAN

Location: MICHIGAN

---

CELRE-OT-T


CONDITION OF FEDERAL NAVIGATION CHANNEL  
NEW BUFFALO HARBOR

1. Condition surveys performed within the Federal navigation channel at New Buffalo Harbor, Michigan during August 2004, indicate shoaling as shown on the back of this sheet.
2. Mariners are urged to use extreme caution in the area.
3. All inquiries should be addressed to CELRE-OT-T and should refer to Notice to Navigation Interests No. L04-64. Internet address: <http://www.lre.usace.army.mil> Go to: Detroit Home Page, Who We Are, Operations Home Page.

DONALD P. LAUZON  
Lieutenant Colonel, U.S. Army  
District Engineer

Notice to the Postmaster:

It is requested that the above notice be conspicuously and continuously posted until November 30, 2004.



THE INFORMATION DEPICTED ON THIS MAP REPRESENTS THE RESULTS OF SURVEYS MADE ON THE DATES INDICATED AND CAN ONLY BE CONSIDERED AS INDICATING THE GENERAL CONDITIONS EXISTING AT THAT TIME.

SURVEYED: AUGUST 2004

SOUNDINGS ARE IN FEET AND ARE REFERRED TO LOW WATER DATUM 576.8 FEET ABOVE MEAN WATER LEVEL AT FATHER POINT, QUEBEC, IGLD, 1955.

 Shoals indicate least available depth below LWD

**NEW BUFFALO HARBOR, MI**

CONDITION OF CHANNEL

ISSUED: 10 SEPTEMBER 2004

U.S. Army Engineer District, Detroit