



**US Army Corps
of Engineers®**

Detroit District
Operations Office
P.O. Box 1027
Detroit, MI 48231-1027
(313) 226-6797
FAX - (313) 226-3519

Notice to Navigation Interests

Notice No. L07-25

Date: 31 MAY 2007

Waterway: LAKE SUPERIOR

Location: MICHIGAN

CELRE-OT-T


CONDITION OF FEDERAL NAVIGATION CHANNEL LITTLE LAKE HARBOR

1. Surveys performed within the Federal navigation channel at Little Lake Harbor, Michigan during May 2007, indicate the conditions shown on the following sheet.
2. Mariners are urged to use extreme caution in the area.
3. Questions regarding this notice may be directed to our Operations Office.
Our internet address is: <http://www.lre.usace.army.mil/who/operationsofficehomepage/>


WILLIAM J. LEADY
Lieutenant Colonel, U.S. Army
District Commander

Notice to the Postmaster:

It is requested that the above notice be conspicuously and continuously posted until November 30, 2007.



PROJECT DEPTH 12.0 FT.
MAINTENANCE DEPTH 8.0 FT.



LAKE SUPERIOR

LITTLE LAKE

APPROXIMATE SHORELINE

THE INFORMATION DEPICTED ON THIS MAP REPRESENTS THE RESULTS OF SURVEYS MADE ON THE DATES INDICATED AND CAN ONLY BE CONSIDERED AS INDICATING THE GENERAL CONDITIONS EXISTING AT THAT TIME.

ALL SOUNDINGS ARE REFERENCED TO IGLD, 1985 FOR LAKE SUPERIOR ELEVATION 601.1 FT. ABOVE MEAN SEA LEVEL AT RIMOUSKI, QUEBEC.



Shoals indicate least available depth below LWD

SURVEYS TAKEN: **MAY 2007**

LITTLE LAKE HARBOR, MICHIGAN

CONDITION OF CHANNEL

ISSUED: **31 MAY 2007**

U.S. Army Engineer District, Detroit