



**US Army Corps
of Engineers®**

Detroit District
Operations Office
P.O. Box 1027
Detroit, MI 48231-1027
(313) 226-6797
FAX - (313) 226-3519

Notice to Navigation Interests

Notice No. L07-44

Date: 8 AUGUST 2007

Waterway: LAKE HURON

Location: MICHIGAN

CELRE-OT-T


CONDITION OF FEDERAL NAVIGATION CHANNEL HARRISVILLE HARBOR

1. Surveys performed during August 2007 indicate shoaling in the Federal navigation channel at Harrisville Harbor, Michigan. As shown on reverse. The surveys are available on our web site. Our internet address is: <http://www.lre.usace.army.mil/who/operationsofficehomepage/>
2. Mariners are urged to use extreme caution in the area.
3. Questions regarding this notice may be directed to our Operations Office.

WILLIAM J. LEADY
Lieutenant Colonel, U.S. Army
District Commander

Notice to the Postmaster:

It is requested that the above notice be conspicuously and continuously posted until November 30, 2007.



Shoals indicate least available depth below LWD

All depths and project depths are referred to Low Water Datum elevation 577.5 ft. above Mean Water Level, IGLD, 1985.

0harris.bmp

The information depicted on this map represents the results of surveys made on the date indicated and can only be considered as indicating the general conditions existing at that time.

Surveys taken: August 2007

HARRISVILLE HARBOR, MICHIGAN

CONDITION OF CHANNEL

ISSUED: 8 August 2007

U.S. Army Engineer District, Detroit